EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	fuse near5 cutout and fuse same (current near5 (sensor or detector)) same (indicator or display or led)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/05/25 14:01
L2	4	(fuse near5 (cutout or holder)) and fuse same (current near5 (sensor or detector)) same (indicator or display or led)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/05/25 14:16
L3	14	(fuse near5 (cutout or holder)) and fuse same (current near5 (sens\$4 or detect\$3)) same (indicator or display or led)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/05/25 14:20
L4	2	337/273,282.ccls. and fuse same (current near5 (sens\$4 or detect\$3)) same (indicator or display or led)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/05/25 14:21
L5	15	340/638.ccls. and fuse same (current near5 (sens\$4 or detect\$3)) same (indicator or display or led)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/05/25 14:21